STATE OF WEST VIRGINIA

Department of Environmental Protection Environmental Enforcement

NOTICE OF VIOLATION

Violation No **W18-49-074-TJC**

To the Operator or Agent of:

Facility Name: **Atlantic Coast Pipeline** Permit No. **WVR310820**

Permittee or Individual: **DOMINION ENERGY TRANSMISSION, INC.**

Located at or near: **Tallmansville**, in **Upshur** County

Representative: LESLIE HARTZ, VICE PRES Date: 6/28/2018 Time: 10:00

Address / phone number: 707 E. MAIN ST., RICHMOND, VA 23219 / 8047714468

Whereas, an inspection of the above named operation by the undersigned, duly authorized agent of the Secretary, at which the following described condition or practice exists, in violation of Chapter <u>22</u>, Article <u>11</u>, Section(s) <u>1 et. Seq.</u> of the Code of West Virginia and/or Section(s) <u>Title 47, Series 2, Section 3.2.b.</u> of the Rules and Regulations and/or Section(s) <u>D & G</u> of the Permit referenced above promulgated thereunder in that you:

Have violated the following terms and conditions of WV/NPDES General Water Pollution Control Permit No. WV0116815, Registration No. WVR310820:

1. Section D.1.- failed to operate and maintain all erosion control devices. Compost filter sock was installed in the roadside ditch along Our Mills Road (1974+61). The installed BMP was not properly operated, which allowed sediment laden water to bypass the BMP.

Temporary slope breakers were not properly operated in areas scattered throughout the inspected area. The slope breakers were installed at steep angles, which caused excessive erosion of the fill slope at the BMP.

2. Section G.4.e.2.A.ii.j: Failed to prevent sediment-laden water from leaving the site without going through an appropriate device. Offsite sediment deposits were noted in areas scattered throughout the inspected area as a result of the deficiencies outlined in item number 1 of the notice of violation.

Have violated the following WV Legislative Rules (Requirements Governing Water Quality Standards):

3. Title 47, Series 2, Section 3.2.b.-Caused conditions not allowable in waters of the State by allowing sediment deposits on the bottom of UNT Grassy Run (38° 54.205' X 80° 12.194').

The following corrective measures were discussed with you at the time of this inspection: Take measures to correct the aforementioned violations.

Within <u>20</u> days provide a written response to the inspector named below, at the address indicated, detailing the actions taken to abate this violation.

Received by:		
Sent Certified I	Mail7018004000004793601	6
Signature		Title
Jim Cook		
Duly Authorized Agent /	(304)288-6219	tim.j.casto@wv.gov
Inspector	Telephone	E-mail

Send Response to the Inspector at the address indicated below:

WV Department of Environmental Protection

Environmental Enforcement / WW

2031 Pleasant Valley Road; Fairmont, WV 26554

SENDER: COMPLETE THIS SECTION A. Signature COMPLETE THIS SECTION ON DELIVERY

so that we can return the card to you Print your name and address on the reverse

Complete items 1, 2, and 3.

Attach this card to the back of the mailpiece, or on the front if space permits.

Article Addressed to:

- Attn: Leslie Hartz mominion Energy Transmission
- Richmond, VA 23219 9590 9402 3080 7124 9867 41 707 E. Main St.
- Article Number (Transfer from service label) 9T09 E62h 0000 0h00 9T02 Collect on Deliver

- . Date of Delivery ☐ Addressee
- D. Is delivery address different from item 1? If XLS, enter delivery address below:

☐ Yes

Collect on Delivery Restricted Delivery Certified Mail Restricted Delivery Certified Mail® Mail Restricted Delivery


] Adult Signature] Adult Signature Restricted Delivery

Registered MailTM Priority Mail Express®

Registered Mail Restricted

Service Type

- Return Receipt for Merchandise Delivery
- Signature Confirmation TM Signature Confirmation Restricted Delivery



Postal Service **United States**